

ANNEXURE D

BUILDING SAFETY CERTIFICATE

No. _____

Dated: 22/03/2024

It is certified that the existing building Woodlumpark P. School (name of the building or premises) at Chunda in Sittiva G.P. (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	3 Floors	3 Floors	NIL	NIL	NIL	NIL

The building is owned/occupied by..... (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of LIDREN, LSGD (Name of Department/ Govt.) on 16/03/2024 (date of inspection) in the presence of Principal (name and address of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 01/03/2023 to 03/03/2024 a period of One year years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
- 2.
- 3.
- 4.

Issued on 22/03/2024 at _____ by _____


* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal: _____

Name: _____

Designation: _____

Name & Address of Department/ Office: _____



[Signature]
22/03/2024